

Photo documentation of the Low Slope Roof Replacement Scope of Work at Saint Paul School

The repair directive and goal were to STOP all existing active leaks to prevent further water damages to the building structure whilst minimizing construction cost. Due to the current commodities situation, the repair roof systems were selected based on immediate availability. Two separate roof systems were installed over the original roofs.

1. Polyglass One-Ply SBS (Elastomeric) Roof system at roofs 4, 5, 8, 9, 10, & 11:
  - Clean, selective removal of top membrane, and prep work,
  - Prep work include removal and replacement of deteriorated wood roof substrate as needed,
  - Installation of the  $\frac{1}{4}$ " thick asphalt recovery board (Polyboard E), via mechanically fastened,
  - Reinstall existing metal flashing and/or install new .04 bronze aluminum roof edge flashing with galvanized cleat,
  - Apply primer, (Polytack High-tack contact adhesive),
  - Install single ply, self-adhered SBS roof membrane as per manufacturer's recommendations.
2. Firestone Low Slope Fire Retardant RubberGard EPDM Roof system at roof 6:
  - Clean and selective removal of loose membrane including miscellaneous removal of remnants of dens-decking,
  - Prep work includes the installation of  $\frac{1}{2}$ " CDX plywood, mechanically fastened,
  - Install new .04 bronze aluminum roof edge flashing with galvanized cleat,
  - Apply primer, bonding adhesives, and splice tape,
  - Install single EPDM roof membrane to match existing.



General overview of existing roof conditions

**Roof 4**



Existing roof conditions



Polyglass One-Ply Roof System Components, (SBS Elastomeric roof membrane over asphalt coverboard)

**Roof 4**




Post Construction: Approximately 1,630 square feet

## Roof 5



Existing roof conditions



Typical Polyglass Single Ply SBS Elastomeric Roof System Components

**Roof 5**



Post Construction: Approximately 1,645 square feet

**Roof 6**



Existing EPDM roof conditions

**Roof 6**



New  $\frac{1}{2}$ " CDX plywood mechanically fastened



Post Construction: Approximately 900 square feet of EPDM Roofing

**Roof 8**



Existing roof conditions




Existing roof conditions, (crack skylight lites)

## **Roof 8**



Roof deck patching with plywood



Coverboard & new aluminum edge flashing




Waterproof existing skylight with membrane

**Roof 8**



Post Construction: Approximately 540 square feet

**Roof 9**



Existing roof conditions

**Roof 9**



Existing roof opening




Roof Deck Patching (Northeast section)

## Roof 9



Roof deck patching (Southeast Section)




Installation of asphalt coverboard

**Roof 9**



Installation of single ply, self-adhered SBS roof membrane



Post Construction: Approximately 1,700 square feet

## Roof 10



Existing roof conditions



Existing mansard roof conditions, North elevation

### **Roof 10 North Mansard**



Deteriorated wood structural membrane, (rafters and header beams)



Selective mansard roof demolition

**Roof 10 North Mansard**



Selective mansard removal and temporary shoring




New wood double 2 x 8 rafters & header beam

**Roof 10 North Mansard**



New  $\frac{3}{4}$ " CDX plywood sheathing

**Roof 10 North Mansard**



Installation of asphalt saturated felt



Installation of GAF Timberline HDZ shingles, charcoal color

## Roof 10



Installation of asphalt coverboard and aluminum edge flashing



Post Construction: Approximately 2,052 square feet

**Roof 11**




Existing roof conditions

**Roof 11**



Installation of asphalt coverboard and aluminum edge flashing



Typical Aluminum Edge Flashing with Cleat

**Roof 11**



Post Construction: Approximately 1,320 square feet